

LIST OF MAPS

3-1	Reach A—D Surface Sediment Sampling Locations (4 Maps)	4-22	Reach A/B—C/D Exceedances of Tri-n-butyltin in Surface Sediment (2 Maps)
3-2	Reach A/B—C/D Subsurface Sediment Sampling Locations (2 Maps)	4-23	Reach A—D Total Organic Carbon Concentrations in Surface Sediment (4 Maps)
3-3	Reach A/B—C/D Surface Sediment Porewater Sampling Locations (2 Maps)	4-24	Reach A—D Grain Size (4 Maps)
3-4	Reach A—D Surface Sample Location and Analysis (4 Maps)	4-25	Reach A/B—C/D Exceedances of Total PCB in Subsurface Sediment (2 Maps)
3-5	Reach A/B—C/D Subsurface Sample Location and Analysis (2 Maps)	4-26	Reach A/B—C/D Exceedances of Total HPAH in Subsurface Sediment (2 Maps)
3-6	Reach A/B—C/D Porewater Location and Analysis (2 Maps)	4-27	Reach A/B—C/D Exceedances of Fluoranthene in Subsurface Sediment (2 Maps)
4-1	Reach A—D Exceedances of Total PCB in Surface Sediment (4 Maps)	4-28	Reach A Exceedances of Chrysene in Subsurface Sediment
4-2	Reach A—D Exceedances of Total HPAH in Surface Sediment (4 Maps)	4-29	Reach A Exceedances of Indeno(1,2,3-cd) pyrene in Subsurface Sediment
4-3	Reach A—D Exceedances of Fluoranthene in Surface Sediment (4 Maps)	4-30	Reach A/B—C/D Exceedances of Total LPAH in Subsurface Sediment (2 Maps)
4-4	Reach A—D Exceedances of Chrysene in Surface Sediment (4 Maps)	4-31	Reach A/B—C/D Exceedances of Phenanthrene in Subsurface Sediment (2 Maps)
4-5	Reach A—D Exceedances of Indeno(1,2,3-cd) pyrene in Surface Sediment (4 Maps)	4-32	Reach A/B—C/D Exceedances of Acenaphthene in Subsurface Sediment (2 Maps)
4-6	Reach A—D Exceedances of Total LPAH in Surface Sediment (4 Maps)	4-33	Reach A/B—C/D Exceedances of Fluorene in Subsurface Sediment (2 Maps)
4-7	Reach A—D Exceedances of Phenanthrene in Surface Sediment (4 Maps)	4-34	Reach A/B—C/D Exceedances of Phenol in Subsurface Sediment (2 Maps)
4-8	Reach A—D Exceedances of Acenaphthene in Surface Sediment (4 Maps)	4-35	Reach A/B—C/D Exceedances of Hexachlorobenzene in Subsurface Sediment (2 Maps)
4-9	Reach A—D Exceedances of Fluorene in Surface Sediment (4 Maps)	4-36	Reach A/B—C/D Exceedances of Bis(2-ethylhexyl) Phthalate in Subsurface Sediment (2 Maps)
4-10	Reach A—D Exceedances of Phenol in Surface Sediment (4 Maps)	4-37	Reach A/B—C/D Exceedances of Butyl Benzyl Phthalate in Subsurface Sediment (2 Maps)
4-11	Reach A—D Exceedances of Hexachlorobenzene in Surface Sediment (4 Maps)	4-38	Reach A/B—C/D Exceedances of Mercury in Subsurface Sediment (2 Maps)
4-12	Reach A—D Exceedances of Bis(2-ethylhexyl) Phthalate in Surface Sediment (4 Maps)	4-39	Reach A Exceedances of Arsenic in Subsurface Sediment
4-13	Reach A—D Exceedances of Butyl Benzyl Phthalate in Surface Sediment (4 Maps)	4-40	Reach A Exceedances of Lead in Subsurface Sediment
4-14	Reach A—D Exceedances of Mercury in Surface Sediment (4 Maps)	4-41	Reach A Exceedances of Zinc in Subsurface Sediment
4-15	Reach A Exceedances of Arsenic in Surface Sediment	4-42	Reach A/B—C/D Exceedances of 4,4'-DDT in Subsurface Sediment (2 Maps)
4-16	Reach A and D Exceedances of Lead in Surface Sediment (2 Maps)	4-43	Reach A/B—C/D Exceedances of 4,4'-DDD in Subsurface Sediment (2 Maps)
4-17	Reach A Exceedances of Zinc in Surface Sediment	4-44	Reach A/B—C/D Exceedances of 4,4'-DDE in Subsurface Sediment (2 Maps)
4-18	Reach B and C Exceedances of 4,4'-DDT in Surface Sediment (2 Maps)	4-45	Reach A/B—C/D Exceedances of Tri-n-butyltin in Subsurface Sediment (2 Maps)
4-19	Reach B and C Exceedances of 4,4'-DDD in Surface Sediment (2 Maps)	4-46	Reach A/B—C/D Exceedances of Arsenic in Porewater (2 Maps)
4-20	Reach B and C Exceedances of 4,4'-DDE in Surface Sediment (2 Maps)	4-47	Reach A/B—C/D Exceedances of Tri-n-butyltin in Porewater (2 Maps)
4-21	Reach A/B—C/D Exceedances of Total 2,3,7,8-TCDD (Equiv) in Surface Sediment (2 Maps)	4-48	Reach A/B—C/D Exceedances of SQS/CSL in Surface Sediment (2 Maps)
		4-49	Reach A/B—C/D Exceedances of LAET/2LAET in Surface Sediment (2 Maps)